All-O-Matic SW-300DC, SW-325DC, & SW-350DC
# How to wire up to a CP-4

Wire the CP-4 to the All-O-Matic board as follows:

Black Wire

White Wire

Blue Wire

Can use +12VDC **or** +24VDC

DO NOT Connect to both!!
Connect **Red** wire to 1 of
the 2 terminals.

Yellow Wire is not needed for this operator.